





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA,AD



- 1 A 963 313 XX
- 2 A 963 054 NU
- 3 A 963 309 NU
- 4 B 960 862 XX
- 6 A 963 314 NU
- 7 B 960 775 NU
- 10 A 963 788 NU
- 11 A 963 375 NU
- 13 A 961 118 NU
- 15 B 960 754 XX
- 15a A 962 713 NU
- 17 A 960 001 NU




CERAMIX BLUE



A 5649 ..

0211 / A 866 390
(+ A 865 612)
Made in Germany







Ideal Standard
Roentgenstrasse 9
54516 Wittlich
Germany





	P	bar	MIN. 0.1		MAX. 5	P 0.2 bar Q 4.4 l/min
	T	°C	MAX. 80		65 55	P 3.0 bar Q 4.7 l/min



			1	2	3	4	5	6	7	8
P	°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
50°C	15°C	47,4	47	44,5	39,9	35,7	33,9	30,7	29,6	
65°C	15°C	61,3	60,7	57,2	50,6	44,6	41,9	37,4	35,9	
85°C	15°C	79,8	79	74	64,8	56,4	52,7	46,3	44,3	